## **CONSTRUCTION PROPOSAL**

Chuck Becker, CBC1259277 mobile: 321.543.7677 2195 N. Tropical Trail, Merritt Island, FL 32953



OWNER INFORMATION	Era Showcase Prop Mgmt - Atten: Nicole	130 Summer Place	321.576.9610	scshowcam@gmail. com	
	Name	Address	Phone	Email	
PROJECT LOCATION	130 Summer Place Merritt Islan	d 32953	2019-27	4/8/2019	
	Address		Job No.	Date	

## **SCOPE OF WORK AND COSTS**

Qty.	Description	Cost	Total
	Repair Scope Cost For Each Balcony Slab Edge		
	1) Provide Drawings Signed/Sealed by Engineer		
	2) Provide Approved Brevard County Permit		
	3) Provide Dumpster Onsite for Demo Debris		
	4) Demo existing 1st & 2nd Floor Screen Porch		
	Panels to Dumpster & Store 2nd Floor Handrails		
	5) Remove up to 48SF of 1st Floor Ceiling Soffit		
	at Slab Edge to be Reinstalled Upon Completion		
	6) Demo, Form, Pour up to 16SF Damaged Slab		
	Along Edge, Includes Existing Rebar Repair		
	7) Strip Formboards		
	8) Install New 1st & 2nd Floor Screen Panels		
	9) Reinstall Existing Handrails & Ceiling Soffit		
	10) Remove Debis from Site		
		TOTAL	

NOTES	Per	balcon	V	
	ana ana		1111	2

Help-U-Build Contractor to provide labor and materials to complete scope as shown above. Individual slab price is calculated based upon repairing 12 slabs. Any variation in less than 12 will require a pricing adjustment. If existing handrail becomes unusable due to damage or condition, add \$145 per slab replacement. Additional slab repair beyond 16" from leading edge may be an additional charge. Does not include any unforeseens. Does not include any paint other than rebar reconditioning.

OWNER ACCEPTANCE	
Signature of Homeowner or Authorized Representative	Date